

ICS Teaching Module: Urodynamic Artefacts 1

Common artefacts in water-filled systems

A Gammie, C D'Ancona, H-C Kuo & P Rosier.



ICS International Continence Society
Teaching Module

International Continence Society (ICS) Guest Speaker: DISCLOSURES

- Andromeda, Digitimer, Laborie, Mediwatch
 - Project sponsorship
- T-Doc LLC
 - Trial sponsorship
- Astellas, Ono Pharma, Vysera, Flexicare
 - Consultancy
- E2L Ltd
 - Royalties from www.UrodynamicsTrainer.com



Sulu sistem ürodinamik incelemelerde sık görülen artefaktlar


Dr. Ahmet Özgür Güçtaş

Sulu sistemlerde sık görülen artefaktlar


Artefakt: Doğal olarak bulunmayan işleme bağlı ortaya çıkan(Oxford)

- Hareket/ Tüpün çarpması
- Hastanın pozisyon deęiřtirmesi
- Vezikal kateterin çıkması
- Rektal kateterin çıkması
- Kateterin yıkanması
- Hattın şiringaya açık olması
- Boş mesane (zayıf yanıt)
- Boş rektal kateter
- Zayıf öksürük yanıtı


Hareket etme/tüpün çarpması




Pozisyon deęişiklięi/tüpün çarpması




Pozisyon değişikliği




Pozisyon deęişiklięi




Pozisyon deęişiklięi




Vezikal kateterin ıkması




Vezikal kateterin çıkması




Vezikal kateterin çıkması




Rektal kateterin ıkması



Rektal kateterin ıkması




Kateterin basınçlı yıkanması



Kateter su ile yıkanmış


Hattın şırıngaya açık olması(su)

Dönüştürücü şırıngaya açık, sinyali söndürüyor




Şırınga vanası kapatılıyor, artefak düzeliyor

Boş mesane (zayıf yanıtı)




Boş rektal kateter(Su)


Rektal kateter sıvı ve ileti kaybediyor




Zayıf öksürük yanıtı



Zayıf öksürük yanıtı



Canlı sinyale zayıf yanıt



TEŞEKKÜRLER